

Service Bulletin

Circolare Tecnica - Technisches Rundschreiben - Circulaire Technique - Circular Tecnica

Date: 24th July 2015

Subject: **Starting gear**

Product: **F3 - B3 - Dragster - Rivale - Stradale**

This Service Bulletin void and replaces the previous one (SB N°149 Posted on 2nd July 2015) were varied terms, priorities and procedure of reimbursement.
We apologize for the inconvenience.

We inform you that there is a new starting gears update for the models listed above

We ask you to provide the intervention ONLY and EXCLUSIVELY on motorcycles that have starting problems, performing the repair of the starting gears under warranty with the new kit Code 8000C2384.

On motorcycles in stock or that don't have starting problems, it MUST NOT be made any intervention.

MATERIALS THAT NEED TO BE ORDERED TO PERFORM THE OPERATION:

- N° 1 piece cod 8000C2384 COMPLETE GEAR STARTER

PROCEDURE FOR REPLACEMENT

- Replace the starting gear in accordance with the information and indications explained in the respective workshop manuals.
 - Make a test drive before the delivery of the motorcycle to the customer.
- Please contact the Technical Service Assistance for every necessity

Procedure for Warranty reimbursement:

Send a Warranty Request for reimbursement of the work performed including all the relevant data regarding the motorcycle, entering the following codes:

- Warranty Type= GC (in case of a motorcycles with warranty expired use GE warranty type)
- Spare part= 8000C2384
- Operation Code: K022 (2 hours)
- Defect Code: 090

Please in the note refer to the service bulletin N°149 rev 1

The reimbursement of the warranty request will be carried out via Invoice as is the normal procedure.

Thank you in advance for your cooperation, for any need you can contact the MV Agusta Service Dept.

Best Regards,
MV AGUSTA MOTOR S.p.A.
Technical Service Department